

3 Ft. Rectangular Weir (36")

Az. Miners Inches

GAGE HT.	0.00	0.01	0.02	0.03	0.04	0.05	0.06	0.07	0.08	0.09	GAGE Change HT. per Tenth	
0.00	0	0	1	2	3	5	6	8	9	11	0.00	13
0.10	13	15	17	19	21	23	26	28	30	33	0.10	23
0.20	36	38	41	44	46	49	52	55	58	61	0.20	29
0.30	64	68	71	74	77	81	84	88	91	95	0.30	34
0.40	98	102	106	109	113	117	121	125	129	133	0.40	38
0.50	137	141	145	149	153	157	161	166	170	174	0.50	42
0.60	179	183	187	192	196	201	205	210	215	219	0.60	45
0.70	224	229	234	238	243	248	253	258	263	268	0.70	49
0.80	273	278	283	288	293	298	303	308	314	319	0.80	52
0.90	324	330	335	340	346	351	356	362	367	373	0.90	54
1.00	379	384	390	395	401	407	412	418	424	430	1.00	57
1.10	435	441	447	453	459	465	471	477	483	489	1.10	59
1.20	495	501	507	513	519	526	532	538	544	550	1.20	62
1.30	557	563	569	576	582	588	595	601	608	614	1.30	64
1.40	621	627	634	640	647	654	660	667	674	680	1.40	66
1.50	687	694	701	707	714	721	728	735	742	749	1.50	68
1.60	755	762	769	776	783	790	798	805	812	819	1.60	70
1.70	826	833	840	847	855	862	869	876	884	891	1.70	72
1.80	898	906	913	920	928	935	943	950	958	965	1.80	74
1.90	973	980	988	995	1003	1011	1018	1026	1033	1041	1.90	
	0.00	0.01	0.02	0.03	0.04	0.05	0.06	0.07	0.08	0.09		