

4 Ft. Rectangular Weir (48")

Az. Miners Inches

GAGE HT.											GAGE Change HT. per Tenth	
	0.00	0.01	0.02	0.03	0.04	0.05	0.06	0.07	0.08	0.09		
0.00	0	1	2	3	4	6	8	10	12	15	0.00	17
0.10	17	20	22	25	28	31	34	37	41	44	0.10	30
0.20	48	51	55	58	62	66	70	74	78	82	0.20	39
0.30	86	91	95	99	104	108	113	118	122	127	0.30	46
0.40	132	137	142	147	152	157	162	167	173	178	0.40	51
0.50	183	189	194	200	205	211	217	222	228	234	0.50	56
0.60	240	246	252	258	264	270	276	282	288	294	0.60	61
0.70	301	307	314	320	326	333	340	346	353	359	0.70	65
0.80	366	373	380	387	393	400	407	414	421	428	0.80	69
0.90	436	443	450	457	464	472	479	486	494	501	0.90	73
1.00	509	516	524	531	539	547	554	562	570	577	1.00	77
1.10	585	593	601	609	617	625	633	641	649	657	1.10	80
1.20	665	673	682	690	698	707	715	723	732	740	1.20	83
1.30	749	757	766	774	783	791	800	809	817	826	1.30	86
1.40	835	844	852	861	870	879	888	897	906	915	1.40	89
1.50	924	933	942	951	961	970	979	988	998	1007	1.50	92
1.60	1016	1026	1035	1044	1054	1063	1073	1082	1092	1102	1.60	95
1.70	1111	1121	1131	1140	1150	1160	1169	1179	1189	1199	1.70	98
1.80	1209	1219	1229	1239	1249	1259	1269	1279	1289	1299	1.80	100
1.90	1309	1319	1329	1340	1350	1360	1370	1381	1391	1401	1.90	
	0.00	0.01	0.02	0.03	0.04	0.05	0.06	0.07	0.08	0.09		